

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY RESTAURANTS-67S96W/26NWSW

Location ID: 334393

Date: 12/6/2023



Location Entrance – Photo #07966



NE Corner of Location – Photo #07967

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY RESTAURANTS-67S96W/26NWSW

Location ID: 334393

Date: 12/6/2023



Wellheads – Photo #07969



Separators – Photo #07970

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY RESTAURANTS-67S96W/26NWSW

Location ID: 334393

Date: 12/6/2023



Tank Battery – Photo #07971



Open-Ended Load Line – Photo #07972