

Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE

Location ID: 334062

Date: 12/6/2023



Dec 6, 2023 at 11:29:52
5649 County Road 306
Parachute CO 81635
United States



Dec 6, 2023 at 11:30:38
Parachute CO 81635
United States

Location Entrance – Photo #08000

Wellheads – Photo #08001

Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE

Location ID: 334062

Date: 12/6/2023



Dec 6, 2023 at 11:32:05
Parachute CO 81635
United States



Dec 6, 2023 at 11:32:43
Parachute CO 81635
United States

Separators – Photo #08003

Tank Battery – Photo #08004

Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE

Location ID: 334062

Date: 12/6/2023



Lack of Stabilization – Photo #08007



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08009