

Work Completion Report

Contractor: Jamm Power Services

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
LORENZ L FEDERAL 30-12 (2023 Seasonal)	Fall	Jamm Power	10/27/2023

Work Summary	Reclamation Type	Land Use
Inspected site. Seeded site.	Final Maint	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance	Normal	No	Location(s): LORENZ L FEDERAL 30-12 Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

<div> <div>Total Area Affected: 43,560 sq ft</div> <div>Seed Mix: Sandy Soil 2 (18.00 lbs)</div> <div>Crop Type:</div> <div>Soil Type: Sandy</div> <div>Stabilization Date:</div> <div>Seeding Date: 10/27/2023</div> <div>Mulch: None</div> <div>Straw Bales: NA</div> <div>Soil Amendment Type: None</div> <div>Soil Amendment Rate: NA</div> <div>Imported Top Soil: NA</div> <div>Top Soil Source: NA</div> <div>General Notes:</div> </div>
--

LOCATION INFO

Location(s) – Name: LORENZ L FEDERAL 30-12

COGCC ID: **329063**
Well APIs at Location: **12316814**
Land Rep: **Colleen Nealy**
Land Owner: **Kirk Magness**
Rec Contractor PO(s): **Jamm Power PO:4501189001**
Vendor PO(s): **Buffalo Brand Seed PO:4501333993**
Billing Notes: **021-14674.01.10**
Legal Address: **(WELD) NWSW 30 3N66W**
Topsoil Source:
Variance Notes:
Private Utility Notes: **Unknown**
Wildlife Restrictions: **Unknown**
General Notes:
COGCC Doc #'s:
Initial Reclaim Complete Date:
Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map
Description:



Photo Name: Seed Mix
Description:



Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:

