

Inspection Photos

Loc: 443255

Operator: **AUSCO PETROLEUM INC**

Inspection Date: 12/12/2023

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the wellsite.



Inspection Photos



Photo 2. The vegetation in the interim reclamation area is well established. Fence posts round this area need to be removed. .



Inspection Photos



Photo 3. Facing toward the tank battery.

