

Inspection Photos
Location Name: Pappenheim 6-62-27-1609BH2
Location ID: 432657





Photo 1 – Chemical Container Label missing



**Photo 2 – Unused Meter Tube and Stainless Tubing –
Unmarked OOSLAT Riser**

Inspection Photos
Location Name: Pappenheim 6-62-27-1609BH2
Location ID: 432657




Photo 3 – Wellhead



Photo 4 – Wellhead Sign

Inspection Photos
Location Name: Pappenheim 6-62-27-1609BH2
Location ID: 432657



Photo 5 – 2" Riser at Wellsite not OOSLAT



Photo 6 – 2" Riser at Wellsite not OOSLAT

Inspection Photos

Location Name: Pappenheim 6-62-27-1609BH2

Location ID: 432657




Photo 7 – 2" Riser not OOSLAT – Unused Wellhead Parts



Photo 8 – Unused Polish Rod Lubricators

Inspection Photos
Location Name: Pappenheim 6-62-27-1609BH2
Location ID: 432657



Photo 9 – Signs at Entrance