

**Inspection Photos**  
**Location Name: Pappenheim C-W2-6-62-27-26**  
**Location ID: 436860**



**Photo 1 – Signs at Entrance**



**Photo 2 – Gas Lift Injection Meters**

**Inspection Photos**  
**Location Name: Pappenheim C-W2-6-62-27-26**  
**Location ID: 436860**



**Photo 3 – Label missing**



**Photo 4 – Label missing**



**Inspection Photos**  
**Location Name: Pappenheim C-W2-6-62-27-26**  
**Location ID: 436860**



**Photo 5 – Wellheads**



**Photo 6 – Tank Battery**

# Inspection Photos

Location Name: Pappenheim C-W2-6-62-27-26

Location ID: 436860



Photo 7 – Tank Battery Signs

Photo 8 – Tank Battery and VRTs



## Inspection Photos

Location Name: Pappenheim C-W2-6-62-27-26

Location ID: 436860



Energy and Carbon Management Commission  
40.45833, -104.31623, 4642.7ft  
12/11/2023 14:13:30

**Photo 9 – Tank Battery**



Energy and Carbon Management Commission  
40.45842, -104.31617, 4643.7ft  
12/11/2023 14:14:15

**Photo 10 – ECDs**

**Inspection Photos**  
**Location Name: Pappenheim C-W2-6-62-27-26**  
**Location ID: 436860**



**Photo 11 – Separators**



**Photo 12 – Separators**



**Inspection Photos**  
**Location Name: Pappenheim C-W2-6-62-27-26**  
**Location ID: 436860**



**Photo 13 – VRU**



**Photo 14 – Capacity Label**

## Inspection Photos

Location Name: Pappenheim C-W2-6-62-27-26

Location ID: 436860



**Photo 15 – Gas Meters**



**Photo 16 – Flare**



**Inspection Photos**  
**Location Name: Pappenheim C-W2-6-62-27-26**  
**Location ID: 436860**



**Photo 17 – Condensate Vault at Flare**



**Photo 18 – Content and Capacity Labels**

## Inspection Photos

Location Name: Pappenheim C-W2-6-62-27-26

Location ID: 436860



Energy and Carbon Management Commission  
40.45811, -104.31572, 4695.7ft  
12/11/2023 14:17:58

**Photo 19 – Wildlife Netting has been installed**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources