

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/8NENE

Location ID: 335795

Date: 12/11/2023



Location Entrance – Photo #08055



Wellheads – Photo #08056

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/8NENE

Location ID: 335795

Date: 12/11/2023



Separators – Photo #08057



Tank Battery – Photo #08059

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/8NENE

Location ID: 335795

Date: 12/11/2023



Unsecured Separator – Photo #08058