

Inspection Photos
Location Name: State Antelope 43-13 PAD
Location ID: 466172



Photo 1 – Sign at Entrance



Photo 2 – Separators



Inspection Photos
Location Name: State Antelope 43-13 PAD
Location ID: 466172



Photo 3 – Gas Lift Injection Meters and Line Heater



Photo 4 – Chemical Container missing Labels

Inspection Photos
Location Name: State Antelope 43-13 PAD
Location ID: 466172



Photo 5 – Maintenance Tank



Photo 6 – Wellheads

Inspection Photos
Location Name: State Antelope 43-13 PAD
Location ID: 466172



Photo 7 – Wellheads

