

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 180-29 Pad

Location # 324097



Photo # 9504 From entrance to location



Photo # 9505 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 180-29 Pad

Location # 324097



Photo # 9506 Location



Photo # 9507 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 180-29 Pad

Location # 324097



Photo # 9508 Location



Photo # 9509 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 180-29 Pad

Location # 324097



Photo # 9510 Chemical tank missing required info



Photo # 9511 Unused equipment

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 180-29 Pad

Location # 324097



Photo # 9512 Debris