

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335578

Date: 12/11/2023



Location Entrance – Photo #08105



Wellheads/Lack of Stabilization – Photo #08107

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335578

Date: 12/11/2023



Separators – Photo #08106



Tank Battery – Photo #08108

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335578

Date: 12/11/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08117