

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335814

Date: 12/11/2023



Location Entrance – Photo #08097



Wellheads – Photo #08098



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335814

Date: 12/11/2023



Separators – Photo #08101



Tank Battery – Photo #08099





## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335814

Date: 12/11/2023



**Lack of Stabilization – Photo #08102**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #08103**