

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335577

Date: 12/11/2023



Location Entrance – Photo #08109



Wellheads – Photo #08111

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335577

Date: 12/11/2023



Separators/Unsecured Door – Photo #08110



Tank Battery – Photo #08112

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335577

Date: 12/11/2023



Lack of Stabilization – Photo #08116



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08117**