

Operator: EXTRACTION OIL & GAS INC

Location Name: Hergert 35-D Pad

Loc ID: 440396

Inspection: 697008362



Exhibit A

CA: Methanol system #3 lacks placards, see attached photo. Install sign to comply with Rule 605.h.

CA Resolution: Operator has appropriately updated placards on Methanol System #3 to comply with Rule 605.h.



Exhibit A

CA: 400 bbl maintenance tank lacks all placards, see attached photo. Install sign to comply with Rule 605.h.

CA Resolution: Operator has appropriately updated placards on Maintenance Tank to comply with Rule 605.h.

CA: Unused pipe fencing on north edge of location, unused pipe and fittings next to supplied air system, see attached photos. Comply with Rule 606.

CA Resolution: Operator has appropriately addressed and cleared trash and unused equipment from the location to comply with Rule 606.