

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 9405 From entrance to location




Photo # 9406 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 9407 Location



Photo # 9408 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 9409 Location



Photo # 9410 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Dec 11, 2023 at 1:17:00 PM
CO

Photo # 9411 Location



Dec 11, 2023 at 1:34:52 PM
CO

Photo # 9412 Stored vehicles & trailers on location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 9413 Stored vehicles, trailers & miscellaneous equipment location



Photo # 9414 Stored vehicles on location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 9415 Stored vehicle on location