

Inspection Photos

API: 099-06909

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 12/15/2023

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the offsite tank battery. There is no sign posted at the tank battery which is off site from the well. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06909 | Date: 12/15/2023

Inspection Photos



Photo 2. Facing toward the tank which is labeled as water. It appears stained soil was removed. A berm was constructed around the tank however bermed soils need to be compacted.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06909 | Date: 12/15/2023

Inspection Photos



Photo 3. There is well sign posted at the wellhead. The well is offsite away from the tank battery and an additional sign should be posted at the tank battery.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06909 | Date: 12/15/2023