

Inspection Photos
Location Name: Kunzman W 5-9
Location ID: 413346



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Kunzman W 5-9
Location ID: 413346



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Kunzman W 5-9
Location ID: 413346



Photo 5 Wellsite.



Photo 6 Battery location.

Inspection Photos
Location Name: Kunzman W 5-9
Location ID: 413346



Photo 7 TB signs, Undesirable dead vegetation inside TB berm.

Photo 8 TB.



Inspection Photos
Location Name: Kunzman W 5-9
Location ID: 413346



Photo 9 Undesirable dead vegetation in & on the TB berm.



Photo 10 Undesirable dead vegetation around the Horizontal Heated Separator.

Inspection Photos
Location Name: Kunzman W 5-9
Location ID: 413346



Photo 11 Undesirable dead vegetation around the Gas Meter Run.




Photo 12 Undesirable dead vegetation around the Horizontal Heated Separator.

Inspection Photos
Location Name: Kunzman W 5-9
Location ID: 413346



Photo 13 Gas Meter Run.



Photo 14 ECD & Horizontal Heated Separator.

