

Inspection Photos
Location Name: John A Kunzman C1
Location ID: 317784



Photo 1 WH sign over run with dead vegetation.

Photo 2 WH over run with dead vegetation.

Inspection Photos
Location Name: John A Kunzman C1
Location ID: 317784



Photo 3 Location over run with dead vegetation.

Photo 4 Wellsite over run with dead vegetation.