

Inspection Photos
Location Name: Whitetaile F-4 PAD
Location ID: 440714



Photo 1 – A-4-9XRLNB Wellhead



Photo 2 – Wellhead Sign does not reflect current Operator

Inspection Photos
Location Name: Whitetail F-4 PAD
Location ID: 440714



Photo 3 – 21-4-9XRLNB Pumping Unit



Photo 4 – 21-4-29XRLNB Wellhead

Inspection Photos
Location Name: Whitetail F-4 PAD
Location ID: 440714



Photo 5 – Wellhead Sign does not reflect current Operator

Photo 6 – ECDs

Inspection Photos
Location Name: Whitetaile F-4 PAD
Location ID: 440714



Energy and Carbon Management Commission
40.52178, -104.33041, 4794.7ft
12/18/2023 10:33:29



Energy and Carbon Management Commission
40.52179, -104.33038, 4795.8ft
12/18/2023 10:33:13

Photo 7 – Tank Battery

Photo 8 – Tank Battery Signs

Inspection Photos
Location Name: Whitetaile F-4 PAD
Location ID: 440714



Photo 9 – Combustors

Photo 10 – Compressor

Inspection Photos
Location Name: Whitetail F-4 PAD
Location ID: 440714



Photo 11 – Production Equipment



Photo 12 – Production Equipment

Inspection Photos
Location Name: Whitetail F-4 PAD
Location ID: 440714



Photo 13 – Production Equipment



Photo 14 – Glycol Units and Separators

Inspection Photos
Location Name: Whitetaile F-4 PAD
Location ID: 440714



Energy and Carbon Management Commission
40.52221, -104.3311, 4791.8ft
12/18/2023 10:37:46

Photo 15 – VRU



Energy and Carbon Management Commission
40.52274, -104.33086, 4768.6ft
12/18/2023 10:40:42

Photo 16 – North Separator

Inspection Photos
Location Name: Whitetaile F-4 PAD
Location ID: 440714



Energy and Carbon Management Commission
40.5228, -104.33056, 4770.6ft
12/18/2023 10:40:57

Photo 17 – Gas Meters