

Inspection Photos
Location Name: Long #22-15-6NCH
Location ID: 441625



Photo 1 loc pic

Photo 2 Well head

Inspection Photos
Location Name: Long #22-15-6NCH
Location ID: 441625



Photo 3 production equipment

Photo 4 TNK BTRY

Inspection Photos
Location Name: Long #22-15-6NCH
Location ID: 441625



Photo 5 Unused/unmarked and not LOTO risers

Photo 6 stained soil due to dumping Fuel pot

Inspection Photos
Location Name: Long #22-15-6NCH
Location ID: 441625



Photo 7 Trash

Photo 8 NFPA placards faded and one missing.