

Inspection Photos
Location Name: CHAMPLIN(HER)#1-1
Location ID: 320211



Photo#1 Production Tanks




Photo#2 Pumpjack

Inspection Photos
Location Name: CHAMPLIN(HER)#1-1
Location ID: 320211



Photo#3 Vertical Separator/Gas Meter



Photo#4 Unlined Pit

Inspection Photos
Location Name: CHAMPLIN(HER)#1-1
Location ID: 320211



Photo#5 Unlined pit