

**Inspection Photos**  
**Location Name: Antelope J-19 PAD**  
**Location ID: 430139**



**Photo 1 – Signs at Entrance**



**Photo 2 – Wellheads**



Inspection Photos  
Location Name: Antelope J-19 PAD  
Location ID: 430139



Photo 3 – Tank Battery Signs



Photo 4 – Tank Battery





**Inspection Photos**  
**Location Name: Antelope J-19 PAD**  
**Location ID: 430139**




**Photo 5 – Tank Battery**



**Photo 6 – Separators**

**Inspection Photos**  
**Location Name: Antelope J-19 PAD**  
**Location ID: 430139**



**Photo 7 – Riser not OOSLAT**