

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: Pappenheim C-W2 6-62-27_26

Loc ID: 436860

Inspection: 696305506



Exhibit A



Exhibit B

CA: Condensate Vault missing Capacity Label at VRU. Condensate Vault missing Capacity, Content Labels at Flare. Install sign to comply with Rule 605.h.

CA Resolution: Signs have been installed to comply with Rule 605.h.