

**Operator: BONANZA CREEK ENERGY**

**Location Name: Antelope P-17 PAD**

**Loc ID: 428964**

**Inspection: 696305520**



**Exhibit A**

**CA:** Chemical Container at Compressor is missing Labels. Install sign to comply with Rule 605.h.

**CA Resolution:** Signs have been installed to comply with Rule 605.h.