

**Inspection Photos**  
**Location Name: Antelope 19**  
**Location ID: 418009**



**Photo 1 – Tank Battery**

**Photo 2 – ECD**

Inspection Photos  
Location Name: Antelope 19  
Location ID: 418009




Photo 3 – Unmarked Risers at ECD

Photo 4 – Unmarked Riser

Inspection Photos  
Location Name: Antelope 19  
Location ID: 418009




Photo 5 – Unmarked Risers and Opened Ended pipe and Stacks





Photo 6 – Unmarked Risers

Inspection Photos  
Location Name: Antelope 19  
Location ID: 418009



**Photo 7 – Unmarked Riser, Opened Ended pipe and Stacks and Unused Meter Tube**

**Photo 8 – Unmarked Riser and Unused Chemical Container**

**Inspection Photos**  
**Location Name: Antelope 19**  
**Location ID: 418009**



**Photo 9 – Wellhead**



**Photo 10 – Unmarked Riser at Wellhead**

**Inspection Photos**  
**Location Name: Antelope 19**  
**Location ID: 418009**



Energy and Carbon Management Commission  
40.38063, -104.37017, 4557.6ft  
12/12/2023 14:26:09



Energy and Carbon Management Commission  
40.38021, -104.3706, 4570.1ft  
12/12/2023 14:26:36

**Photo 11 – Wellhead Sign**

**Photo 12 – Tank Battery**

Inspection Photos  
Location Name: Antelope 19  
Location ID: 418009



Photo 13 – Tank Battery Signs