

Inspection Photos
Location Name: Antelope D-18 PAD
Location ID: 428713



Photo 1 – Separators and ECD




Photo 2 – ECD – Unmarked Risers and Unused Pipe

Inspection Photos
Location Name: Antelope D-18 PAD
Location ID: 428713



Photo 3 – Wellheads



Photo 4 – Unmarked Risers

Inspection Photos
Location Name: Antelope D-18 PAD
Location ID: 428713




Photo 5 – Unmarked Risers



Photo 6 – Unmarked Risers

Inspection Photos
Location Name: Antelope D-18 PAD
Location ID: 428713




Photo 7 – Unmarked Risers

Photo 8 – Tanks

Inspection Photos
Location Name: Antelope D-18 PAD
Location ID: 428713



Energy and Carbon Management Commission
40.39364, -104.36987, 4547.5ft
12/12/2023 14:32:06



Energy and Carbon Management Commission
40.39347, -104.37003, 4553.3ft
12/12/2023 14:32:32

Photo 9 – Tank Battery Signs

Photo 10 – Unused Pipe and Fitting inside Tank Berm

Inspection Photos
Location Name: Antelope D-18 PAD
Location ID: 428713



Photo 11 – Unmarked Risers at Tanks

Photo 12 – Unmarked Risers Tank

Inspection Photos
Location Name: Antelope D-18 PAD
Location ID: 428713




Photo 13 – NE Tank Content and Capacity Labels

Photo 14 – Separators

Inspection Photos
Location Name: Antelope D-18 PAD
Location ID: 428713



Photo 15 – Separator is open to Atmosphere. Unused Meter Tube, Pipe, Fittings and Heat Stack. Unmarked Risers

Photo 16 – Separator is open to Atmosphere. Unused Meter Tube, Pipe, Fittings and Heat Stack. Unmarked Risers

Inspection Photos
Location Name: Antelope D-18 PAD
Location ID: 428713



Energy and Carbon Management Commission
40.3935, -104.37045, 4548.9ft
12/12/2023 14:34:17



Energy and Carbon Management Commission
40.3934, -104.37033, 4544.8ft
12/12/2023 14:34:31

Photo 17 – Separator is open to Atmosphere. Unused Meter Tube, Pipe, Fittings and Heat Stack. Unmarked Risers. Tumbleweed Debris

Photo 18 – Separators