

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Photo 1 – North Gas Lift Injection House and Line Heater



Photo 2 – Chemical (Methanol) Containers

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Photo 3 – MT 45 Missing Labels



Photo 4 – MT 45 Missing Labels

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Photo 5 – South Gas Lift Injection Meter house and Line Heater




Photo 6 – Chemical Container Missing Labels

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Photo 7 – North Wellheads



Photo 8 – North Wellheads

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Energy and Carbon Management Commission
40.4327, -104.29914, 4371.4ft
12/18/2023 11:22:12

Photo 9 – South Wellheads



Energy and Carbon Management Commission
40.43266, -104.2996, 4591.1ft
12/18/2023 11:23:44

Photo 10 – Gas Meter House and Pig Line

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Photo 11 – Electrical Panels and Instrumental Air Units



Photo 12 – Separators

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Photo 13 – Maintenance Tank




Photo 14 – Label does not reflect current Operator

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Photo 15 – Separators



Photo 16 – Instrumental Air Units

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Photo 17 – Sign at Entrance