

Final Reclamation and Stormwater Inspection

Date: 12/06/2023

Operator: Noble Energy INC - 100322

Location ID: 409315

Inspection Document #: 708200766

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Timmerman #44-18
Location ID: 409315



Photo 1. Taken from the northern portion of the former well location. Photo illustrates the presence of weedy debris/undesirable vegetation (e.g. russian thistle and kochia). Additional reclamation activities are required.

Inspection Photos
Location Name: Timmerman #44-18
Location ID: 409315



Photo 2. Taken from the western portion of the former well location. See comments in Photo 1.

Inspection Photos
Location Name: Timmerman #44-18
Location ID: 409315



Photo 3. Taken from the southern portion of the former well location, facing northwest. See comments in Photo 1.

Inspection Photos
Location Name: Timmerman #44-18
Location ID: 409315



Photo 4. Taken from the northwestern portion of the former well location. Photo illustrates the adjacent reference area (left of red line) and the disturbance area (right of red line) that requires additional reclamation activities. .