

Operator: BONANZA CREEK ENERGY

Location Name: Antelope 14-19 Pad

Loc ID: 413458

Inspection: 696305536



Exhibit A



Exhibit B

CA: Unmarked OOSLAT Risers at 14-19 Wellhead. Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

CA Resolution: Risers have been marked to comply with Rule 1105.