

Operator: BONANZA CREEK ENERGY

Location Name: Antelope J-19 PAD

Loc ID: 430139

Inspection: 696305534



Exhibit A

CA: Unmarked OOSLAT Risers at Line Heater; see photos Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

CA Resolution: Risers have been marked to comply with Rule 1105.