

**Operator: BONANZA CREEK ENERGY**

**Location Name: Antelope T-18 PAD**

**Loc ID: 435653**

**Inspection: 696305528**



**Exhibit A**

**CA:** Chemical Container at Gas Lift Injection Meter House is missing labels; labels have weathered away no longer visible. Install sign to comply with Rule 605.h.

**CA Resolution:** Signs have been installed to comply with Rule 605.h.



**Exhibit A**

**CA:** Unused Chemical Containers at South Side on Location. Comply with Rule 606

**CA Resolution:** Unused Chemical Containers have been removed to comply with Rule 606.