

Inspection Photos
UPRR 42 Pan Am F #4
Spill ID 480343/Remediation Project No 25934



Photo 1 – Open excavation.



Photo 2 - Open excavation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
UPRR 42 Pan Am F #4
Spill ID 480343/Remediation Project No 25934



Photo 3 – Fencing/weeds.



Photo 4 - Fencing/weeds.



Inspection Photos
UPRR 42 Pan Am F #4
Spill ID 480343/Remediation Project No 25934



Photo 5 – Fencing/weeds.



Photo 6 - Fencing/weeds.



Inspection Photos
UPRR 42 Pan Am F #4
Spill ID 480343/Remediation Project No 25934



Photo 7 – Fencing/weeds.



Photo 8 - Fencing/weeds.

