

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV-67S95W/5NWNW

Location ID: 334627

Date: 12/18/2023



Location Entrance – Photo #08253

Wellheads – Photo #08254

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV-67S95W/5NWNW

Location ID: 334627

Date: 12/18/2023



Dec 18, 2023 at 13:13:57
Parachute CO 81635
United States



Dec 18, 2023 at 13:14:15
Parachute CO 81635
United States

Separators – Photo #08257


Tank Battery – Photo #08258

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV-67S95W/5NWNW

Location ID: 334627

Date: 12/18/2023



Open Cellar – Photo #08255

Open Cellar – Photo #08256

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV-67S95W/5NWNW

Location ID: 334627

Date: 12/18/2023



Lack of Stabilization – Photo #08259



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08260**