

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/20/2023

Submitted Date:

12/20/2023

Document Number:

696305580

FIELD INSPECTION FORM

Loc ID 317522 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10773
Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC
Address: 5251 DTC PKWY STE 950
City: GREENWOOD State: CO Zip: 80111

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-------------------------------|------------|
| Parrish, Melissa | 970-397-3896 | mparrish@fundareresources.com | |
| Smith, Sydney | | ssmith@fundareresources.com | Regulatory |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 238909 | WELL | SI | 09/01/2014 | GW | 123-05786 | NELSON RANCHES 4 | TA |

General Comment:

Inspected Facilities

Facility ID: 238909 Type: WELL API Number: 123-05786 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA - TA/SI Since 09.01.2014. Last MIT 10.31.2018. 5-Year MIT Over due. Per Rule 417.c.(2)
Well was found in state of Temporary Abandonment. Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.

Corrective Action: Perform a successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. **Date:** _____

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| Inspection at Fundare Resources Operating Company LLC, Nelson Ranches 4, at Location 317522 in Weld County, Colorado. While there, I observed Production Operations. TA - Last MIT 10.31.2018. 5-Year MIT Overdue. Per Rule 417.c.(2) | petrie | 12/20/2023 |