

# Inspection Photos

API: 043-06194

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 12/21/2023

County: FREMONT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest toward the wellsite location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:417859 | Date: 12/21/2023



## Inspection Photos



**Photo 2.** Facing southeast toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:417859 | Date: 12/21/2023



## Inspection Photos



**Photo 3.** Facing back northwest. There is an offsite tank battery shown at red arrow..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:417859 | Date: 12/21/2023



## Inspection Photos



**Photo 4.** Standing at the tank battery facing south. The well is shown at red arrow. The flowline does not appear to be registered.





## Inspection Photos



**Photo 5.** There are weed debris inside the tank battery that needs to be removed. There is not a proper sign posted at the tank battery.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:417859 | Date: 12/21/2023



## Inspection Photos



**Photo 6.** Facing southwest toward the offsite tank battery which has 6 tanks. There is not a proper sign posted at the tank battery.

