

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WPX Energy RMV 108-4 Pad

Location ID: 323991



Photo # 98 From entrance to location



Photo # 99 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WPX Energy RMV 108-4 Pad

Location ID: 323991



Photo # 100 Location



Photo # 101 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WPX Energy RMV 108-4 Pad

Location ID: 323991



Photo # 102 Location



Photo # 103 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WPX Energy RMV 108-4 Pad

Location ID: 323991



Photo # 104 Location



Photo # 105 Unmarked/improperly marked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WPX Energy RMV 108-4 Pad

Location ID: 323991



Photo # 106 Wellhead sign weathered & illegible



Photo # 107 Multiple wellhead signs weathered & illegible



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WPX Energy RMV 108-4 Pad

Location ID: 323991



Photo # 108 Multiple wellhead signs weathered & illegible



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources