

Inspection Photos

Loc: 322216

Operator: **JAVERNICK OIL**

Inspection Date: 12/21/2023

County: **FREMONT**



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing toward the wellsite.



Inspection Photos



Photo 2. There is unused supplies and cement blocks stored at the west side of the location.



Inspection Photos



Photo 3. Facing north at the location. There is an unused equipment trailer with drilling pipe, cement blocks stored on the location that needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322216 | Date: 12/21/2023