

FORM
INSPRev
X/20

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/13/2023

Submitted Date:

12/22/2023

Document Number:

694100244

FIELD INSPECTION FORM

Loc ID 319419 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10547
Name of Operator: HELENA RESOURCES INC
Address: 2960 SIMMS DR
City: LAKEWOOD State: CO Zip: 80215

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Pagano, Theodore	(970) 590-3944	tapagano@helena-resources.com	
Raney, Jeremy	303-775-3647	Jer.raney@gmail.com	

General Comment:

This is an environmental inspection for Location ID 319419 Thurman Hays 1 pad. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: Statewide unnecessary equipment, weeds, waste, and trash requirements, recliner, piping, empty boxes etc.

Corrective Action: Comply with Rule 606

Date: 01/05/2024

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____
 Comment: No spills present at time of inspection.
 Corrective Action: Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100245	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6370239