

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 287 From entrance to location




Photo # 288 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738

Dec 19, 2023 at 12:45:33 PM



Photo # 289 Location

Dec 19, 2023 at 12:37:02 PM
CO



Photo # 290 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 291 Location



Photo # 292 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Dec 19, 2023 at 12:36:01 PM
CO

Photo # 293 Barbed wire fence needs maintenance/wildlife hazard



Dec 19, 2023 at 12:36:06 PM
CO

Photo # 294 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 295 Barbed wire fence needs maintenance/wildlife hazard



Photo # 296 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 297 Hole in liner/liner needs maintenance



Photo # 298 Hole in liner/liner needs maintenance



Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 299 Hole in liner/liner needs maintenance



Photo # 300 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 301 Hole in liner/liner needs maintenance




Photo # 302 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738




Photo # 303 Hole in liner/liner needs maintenance



Photo # 304 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 305 Hole in liner/liner needs maintenance



Photo # 306 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 307 Hole in liner/liner needs maintenance



Photo # 308 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 309 Hole in liner/liner needs maintenance



Photo # 310 Hole in liner/liner needs maintenance



Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 311 Hole in liner/liner needs maintenance



Photo # 312 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 10-1 (RA10) Pad

Location #: 334738



Photo # 314 Hole in liner/liner needs maintenance