

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE D31 595 Pad

Location #: 335674



Dec 21, 2023 at 10:14:07 AM



Dec 21, 2023 at 10:37:33 AM

Photo # 420 From entrance to location

Photo # 421 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE D31 595 Pad

Location #: 335674



Photo # 422 Location



Photo # 423 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE D31 595 Pad

Location #: 335674



Photo # 424 Location



Photo # 425 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE D31 595 Pad

Location #: 335674



Photo # 426 Open wellhead cellar



Photo # 427 Open wellhead cellar



Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE D31 595 Pad

Location #: 335674



Photo # 428 Open wellhead cellar



Photo # 429 Open wellhead cellar