

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Photo # 526 From entrance to location



Photo # 527 From entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Photo # 528 Location



Photo # 529 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Photo # 530 Location



Photo # 531 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Photo # 532 Unmarked deadman



Photo # 533 Same unmarked deadman from a different angle

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF03B19 D19A 595 Pad

Location # 335905



Photo # 534 Unused equipment