

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)

Well Name Doheny-Schroeder 2 API Number 05 - (687-5797)
Operator Frank H. Walsh Permit # 60 0000
Location SENE 7-2N-57W County Morgan
Field _____ Inspector EBB



AL/PA/DA Inspection Results: Well Status: 99999999
Pass(Y) _____ Fail(N) X Date 10/29/91 ND _____ DG _____ WO _____ PR _____ SI _____ TA _____

=====

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 3-11-74 Date Permit Expired: _____
Hole Plugged: Yes ✓ No _____ Pits Backfilled: Yes _____ No X
Material Buried: Yes _____ No X N/A _____ Site Clean: Yes _____ No X
Bond Release OK: Yes _____ No X Fed _____ Hole Marker: Yes _____ No X

Date of Safety/Status Inspection _____

Comments: flow field around site - (risers)



00080032

Violations: Yes ✓ No _____ Notice Sent: Yes ✓ No _____ Date Sent: 11-1-91