

Final Reclamation Inspection

December 14, 2023

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC- #8960

Location ID: 440344

Inspection Document #: 697505024

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Crow Valley 31-18 Pad
Location ID: 440344




Photo 1. ECMC 2013 aerial imagery illustrates the Location was not yet constructed.



Inspection Photos
Location Name: Crow Valley 31-18 Pad
Location ID: 440344




Photo 2. ECMC 2015 aerial imagery illustrates the Location was constructed.



Inspection Photos
Location Name: Crow Valley 31-18 Pad
Location ID: 440344




Photo 3. Photo illustrates the Operator Construction Layout Drawing.



Inspection Photos

Location Name: Crow Valley 31-18 Pad

Location ID: 440344




Photo 4. Google Earth aerial imagery from 8/2/2023. The corner Lat/Long's from the Construction Layout Drawing were plotted on Google Earth to demonstrate the Location was built for oil and gas purposes.



Inspection Photos
Location Name: Crow Valley 31-18 Pad
Location ID: 440344



Photo 5. Photo illustrates the Location appeared to be built but a locked gate/no trespassing sign prevented Staff from confirming; therefore, Staff used historic aerial imagery to confirm.

