

Final Reclamation Inspection

December 14, 2023

Operator: NOBLE ENERGY INC - #100322

Location ID: 310184

Inspection Document #: 6697505026

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: KEHN-USX AD-67N62W 19NESW

Location ID: 310184



Photo 1. Photo taken from the location entrance off SH392, facing East. Photo illustrates gravel remains, unmanaged weeds, gates and cattle guard have not been removed.



Photo 2. Photo taken of the gates and cattle guard.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 6697505026

Inspection Photos

Location Name: KEHN-USX AD-67N62W 19NESW

Location ID: 310184



Photo 3. Photo taken from the cattle guard, facing North. Photo illustrates perimeter fencing has been removed; therefore, the gates and cattle guard serve no purpose, and need to be removed.



Photo 4. Photo taken from the cattle guard, facing South. See comments under Photo 3.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 6697505026

Inspection Photos

Location Name: KEHN-USX AD-67N62W 19NESW

Location ID: 310184



Photo 5. Photo taken from the southern access road, facing East. Photo illustrates unmanaged weeds with little to no establishment of desirable perennial vegetation.

Note- Russian wildrye appears to have been planted, which is an introduced species not reflective of reference areas. Russian wildrye appears to be spreading onto reference areas.



Photo 6. Close up photo taken of Russian wildrye within unmanaged weeds.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 6697505026

Inspection Photos

Location Name: KEHN-USX AD-67N62W 19NESW

Location ID: 310184



Photo 7. Photo taken from a portion of the access road, facing East. Photo illustrates unmanaged weeds and bare soil.



Photo 8. Photo taken from the well location, facing West. Photo illustrates the well location in the foreground and reference area vegetation in the background. Photo highlights the vegetative growth of the introduced grass species and how that differs from reference area vegetative growth.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 6697505026

Inspection Photos

Location Name: KEHN-USX AD-67N62W 19NESW

Location ID: 310184



Photo 9. Photo taken from the well location, facing North. See comments under Photo 8.



Photo 10. Photo taken from the well location, facing South. See comments under Photo 8.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 6697505026

Inspection Photos

Location Name: KEHN-USX AD-67N62W 19NESW

Location ID: 310184



Photo 11. Reference area photo illustrates native, perennial vegetation which is not observed throughout disturbance areas.