

# Interim Reclamation and Stormwater Inspection

Date: 12/20/2023

Operator: BISON IV OPERATING LLC - 10670

Location ID: 469100

Inspection Document #: 708200772

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Goldeneye Center Pad  
Location ID: 469100



**Photo 1.** Stained soil observed near tank battery connections.



Inspection Photos  
Location Name: Goldeneye Center Pad  
Location ID: 469100



**Photo 2.** Taken from the northern production areas. The interim areas consist of undesirable vegetation (e.g. kochia and russian thistle), which is the predominant vegetative cover. Additional weed management/revegetation activities are required in order to comply with Rule 1003 standards.

Inspection Photos  
Location Name: Goldeneye Center Pad  
Location ID: 469100



**Photo 3.** Northern interim areas, facing west. See comments in Photo 2.



Inspection Photos  
Location Name: Goldeneye Center Pad  
Location ID: 469100



**Photo 4.** Northern interim areas, facing south. See comments in Photo 2.

Inspection Photos  
Location Name: Goldeneye Center Pad  
Location ID: 469100



**Photo 5.** Northern interim areas, facing northeast. See comments in Photo 2.



Inspection Photos  
Location Name: Goldeneye Center Pad  
Location ID: 469100



**Photo 6.** Western interim areas, facing north. See comments in Photo 2.



Inspection Photos  
Location Name: Goldeneye Center Pad  
Location ID: 469100



**Photo 7.** Taken near the southwest corner of the location, facing east. See comments in Photo 2.



Inspection Photos  
Location Name: Goldeneye Center Pad  
Location ID: 469100



**Photo 8.** Southern interim areas, facing west. See comments in Photo 2.

Inspection Photos  
Location Name: Goldeneye Center Pad  
Location ID: 469100



**Photo 9.** Taken near the southeast corner of the location, facing north. See comments in Photo 2.