

## WELL SITE INSPECTION FORM



WELL NAME Davie (RE) 4  
OPERATOR Snowden  
LOCATION SENE 12-2N-55W  
FIELD Jubilee

API NUMBER 05 - 087 - 7575  
PERMIT NUMBER 810096  
COUNTY Morgan  
INSPECTOR Burley

## AL/PA/DA INSPECTION RESULTS:

PASS(Y) \_\_\_\_\_ FAIL(N) ☒ DATE 9-26-88 FN \_\_\_\_\_ FD \_\_\_\_\_ WO \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING DRILLING \_\_\_\_\_

CASING SIZE \_\_\_\_\_ DEPTH SET \_\_\_\_\_ CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_  
CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_  
RIG \_\_\_\_\_ BOP'S \_\_\_\_\_ CONTACT \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_  
DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_  
TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_  
SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls  
EQUIPMENT \_\_\_\_\_

BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_  
METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

## AL/PA/DA INSPECTION

DATE PLUGGED: 9-29-87 DATE PERMIT EXPIRED: \_\_\_\_\_  
HOLE PLUGGED: YES ☒ NO \_\_\_\_\_ PITS BACKFILLED: YES ☒ NO \_\_\_\_\_  
MATERIAL BURIED: YES \_\_\_\_\_ NO ☒ NA \_\_\_\_\_ SITE CLEAN: YES \_\_\_\_\_ NO ☒  
BOND RELEASE OK: YES \_\_\_\_\_ NO ☒ FED \_\_\_\_\_ HOLE MARKER: YES \_\_\_\_\_ NO ☒

DATE OF SAFETY/STATUS INSPECTION \_\_\_\_\_

COMMENTS pipe on site, anchors, trash



00075564