

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: ANTELOPE 18I TB**

**Loc ID: 418173**

**Inspection: 696305524**



Exhibit A



Exhibit B



**Exhibit C**

**CA:** West Side Tanks - NFPA Labels have all faded and peeled; no longer visible. See photos Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has appropriately updated and installed NFPA labels on identified tanks to comply with Rule 605.h.

**CA:** Unused Separator Parts and Equipment at Separators; see photos Comply with Rule 606.

**CA Resolution:** Operator has appropriately addressed and removed unused equipment from location to comply with Rule 606.




Exhibit A




Exhibit B



Exhibit C



Exhibit D





Exhibit E



Exhibit F



**Exhibit G**

**CA:** Unmarked 2" and 1" Risers at Separators and 1" Risers at Wellhead. See photos Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

**CA Resolution:** Operator has appropriately marked all identified Risers at Separators and Wellhead.