

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: Pappenheim 6-62-27 NWNW

Loc ID: 432657

Inspection: 696305503



Exhibit A

CA: Container at Gas Lift Injection Meter is missing Label. See photos. Install sign to comply with Rule 605.h.

CA Resolution: Operator has appropriately updated and installed label on chemical container to comply with Rule 605.h.



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: 2" Risers at Wellsite and Gas Lift Meters disconnected flowline risers not OOSLAT. See photos. Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

CA Resolution: Operator has appropriately marked all identified Risers on location.



Exhibit A



Exhibit B

CA: Unused Equipment at Gas Lift Meter and at Wellhead. See photos. Comply with Rule 606.

CA Resolution: Operator has appropriately addressed and removed unused equipment from location to comply with Rule 606.