

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope D-18

Loc ID: 428713

Inspection: 696305541



Exhibit A



Antelope D-18 photo #14

Exhibit B



Exhibit C



Exhibit D



Exhibit E




Exhibit F

CA: Northeast Crude Oil Tank - Content and Capacity Labels have faded no longer visible. See photos Install sign to comply with Rule 605.h.

CA Resolution: Operator has appropriately added/updated labels on NE Crude Oil Tank to comply with Rule 605.h.

CA: Tumbleweed Debris at Separators. See Comply with Rule 606

CA Resolution: Identified tumbleweed debris will consistently be cleared to help maintain the location and comply with Rule 606.

CA: Unused Pipe, Fitting, Parts and Heat Stacks at Tanks and Separators. See photos Comply with Rule 606.

CA Resolution: Operator has appropriately removed identified, unused equipment from the location to comply with Rule 606.

CA: All 3 Separators are open to Atmosphere. All Open-ended openings shall be covered at Pipe, Valves and where Heater Stacks were removed. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

CA Resolution: Operator has appropriately addressed the (3) Separators that are open and effectively installed coverage to prevent unauthorized discharge to comply with Rule 902.b.