

Final Reclamation Inspection

December 15th, 2023

Operator: Simcoe LLC - 10749

Location ID: 326622

Inspection Document #: 714000240

La Plata County, CO

Township: NWNE 24 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fassett 24-01 2
Location ID: 326622

12/15/23
+37.182837,-107.777332
139° SE




Photo 1. View of the well disturbance from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-084249

Inspection Photos
Location Name: Fassett 24-01 2
Location ID: 326622



Photo 2. View of weedy debris at the pump jack.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Fassett 24-01 2
Location ID: 326622

12/15/23
+37.182499,-107.777411
323° NW



Photo 3. Interim vegetation was not fully assessed due to snowy conditions.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515