

Final Reclamation Inspection

December 15th, 2023

Operator: Simcoe LLC - 10749

Location ID: 325927

Inspection Document #: 714000245

La Plata County, CO

Township: SWSE 23 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Picolli A 1
Location ID: 325927

12/15/23
+37.170071,-107.792826
81° E



Photo 1. View of the well disturbance from the entrance facing center.

Inspection Photos
Location Name: Picolli A 1
Location ID: 325927



Photo 2. View of weedy kochia debris observed on the eastern edge of the disturbance.



Inspection Photos
Location Name: Picolli A 1
Location ID: 325927



Photo 3. View of debris observed on location.



Inspection Photos
Location Name: Picolli A 1
Location ID: 325927



Photo 2. View of rill erosion observed forming on the northern fill slope interim area which also lacks vegetation needed for stabilization.

